

Iris Figure 3 on page 1

Fuse and slump the top and bottom portion of the iris separately.

Crest

Diagram at 100% scale

Leaf


Top Part Petal

See page 41 for information on joining multi-part flowers.

Bottom Part Petal


Fire the constructed flower to a contour fuse. A suggested firing schedule can be found in Table 1 on page 38. Slump the fused bottom part of the Iris on mold GM58 using the suggested firing schedule found in Table 5 on page 38. Drape the top part of the Iris over GM57 using the firing schedule found in Table 5 on page 38.

Placement Step One



Arrange the three Leaf pieces and the Top Part Petals as shown above.

Placement Step Two



Place the Bottom Part Petals over the seams between the Leaf pieces. Place the Crest pieces between and over the Top Part Petals as shown above.

Required Glass Pieces

- 3 Top Part Petals
- 3 Crest
- 3 Bottom Part Petal
- 3 Leaf

Molds Used
GM58 & GM57